

OUT 55506

1965 APR 19 22 34Z

1. CAMERA B 122 WAS USED IN MISSION 8011 FLOWN ON 16 APRIL 1965.
PROCESSING WAS PERFORMED BY NAV RECON TECH SUPPCEN.

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: FRAMES 001 TO 240 CONTAIN A NARROW PLUS DENSITY STREAK AND ASSOCIATED SMALL EMULSION GOUGES 1.50" FROM AND PARALLEL TO THE OUTBOARD EDGE OF THE FILM. THE SPACING BETWEEN THE GOUGES IS 6.30" AND THEY ARE ON LINE WITH THE STREAK. THE SAME PLUS DENSITY STREAK WITHOUT EMULSION GOUGES IS PRESENT IN FRAMES 241 TO 723. IT IS NOT DETECTABLE THEREAFTER BUT A SIMILAR FINE STREAK APPEARS IN FRAMES 964 TO 1709, 2.75" FROM THE OUTBOARD EDGE. A PARALLEL PLUS DENSITY STREAK, 2.10" FROM THE OUTBOARD EDGE, IS NOTED IN FRAMES 1445 TO 1709. FRAMES 1304, 1305 AND 1503 CONTAIN LARGE BLISTERS. A HEAT SPLICE IS PRESENT IN FRAME 758.

C. SL SIDE: FRAME 877 CONTAINS ELISTERS. A HEAT SPLICE AND ASSOCIATED HANDLING MARKS ARE PRESENT IN FRAME 877 AND BETWEEN FRAMES 1205/1206. FRAME 1615 CONTAINS A MANUFACTURER'S SPLICE.

D. BOTH SIDES: BOTH EDGES CONTAIN CONTINUOUS SMALL STATIC DISCHARGES AND FINE EDGE FOG. AN IRREGULAR PLUS DENSITY STREAK APPEARS INTERMITTENTLY ALONG THE INBOARD EDGE AND RANGES FROM 0.75" TO 1.50", INBOARD AND ROUGHLY PARALLEL TO THE EDGE. THE TITLED FRAMES ARE NUMBERED 0001 TO 1709.

20 APR 1965

[illegible]

GROUP 1
Excluded from automatic
downgrading and
declassification

SECRET

-2-

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUD COVER OBSCURES APPROXIMATELY 5 PERCENT OF THE PHOTOGRAPHY.

GP-1

S E C R E T

/END OF MESSAGE/

1